RISK ASSESSMENT



ULTRA007

4 Forseeable Hazards

	HAZARD	RISK RATING		
		LOW	MEDIUM	HIGH
1	Slips, trips,falls			V
2	Electric Shocks			V
3	Hand Injuries	V		
4	Back/Arm injuries from manual handling of machine		V	
	-			

5 CONTROLS REQUIRED

Hazard	Essential Controls	Okay with controls
1	Proper training on safe methods of relevant staff	\checkmark
	Appropriate signage warning third parties	
	All relevant staff to wear suitable non-slip footwear	
7	2 Vacuum cleaner to be inspected prior to every use	V
	Vacuum cleaner to be PAT tested annually and labelled	
	Vacuum cleaner to be inspected quarterley in H & S audit by contract manager	
	Proper training of relevant staff on safe use especially	
	cable positioning	
	3 Provision of suitable gloves to relevant staff	<u> </u>
	Proper training on safe method of task	
	4 Staff not to lift appliance if beyond capability	
	Proper training on safe use techniques to relevant staff	
	Regular supervision of relevant staff	