

RISK ASSESSMENT



ULTRA006

4 Foreseeable Hazards

HAZARD	RISK RATING		
	LOW	MEDIUM	HIGH
1 Slips, trips, falls			√
2 Electric Shocks			√
3 Hand Injuries	√		
4 Back/Arm injuries from manual handling of machine		√	
5 Chemical Irritation	√		

5 CONTROLS REQUIRED

Hazard	Essential Controls	Okay with controls
1	Proper training on safe methods of relevant staff Buffer to be inspected quarterley in health & safety audit by contract manager Appropriate signage warning third parties All relevant staff to wear suitable non-slip footwear	√
2	Buffer to be inspected prior to every use Buffer to be PAT tested annually and labelled Proper training of relevant staff on safe use especially cable positioning	√
3	Provision of suitable gloves to relevant staff Proper training on safe method of task	√
4	Staff not to lift appliance if beyond capability Proper training on safe use techniques to relevant staff Regular supervision of relevant staff	√