



RISK ASSESSMENT

ULTRA026

4 Forseeable Hazards

HAZARD	RISK RATING		
	LOW	MEDIUM	HIGH
1 Slips, trips, falls			√
2 Electric Shocks			√
3 Hand Injuries			
4 Chemical Irritation		√	
5 Back/Arm injuries from manual handling of machine	√	√	

5 CONTROLS REQUIRED

Hazard	Essential Controls	Okay with controls
1	Proper training on safe methods of relevant staff Appropriate signage warning third parties All relevant staff to wear suitable non-slip footwear	√
2	Vacuum cleaner to be inspected prior to every use Vauum cleaner to be inspected quarterley in Health and Safety audit by contract manager. Buffer to be PAT tested annually and labelled Proper training of relevant staff on safe use especially cable positioning	√
3	Provision of suitable gloves to relevant staff Proper training on safe method of task	√
4	Full COSHH assessment of chemicals to be used non-hazardous product where possible provision of appropriate personal protective equipment to relevant staff	
5	Staff not to lift appliance if beyond capability Proper training on safe use techniques to relevant staff Regular supervision of relevant staff	√