RISK ASSESSMENT /METHOD STATEMENT



ULTRA020

METHOD SATEMENT

- 1. TASK Refrigerator, cool cabinet and freezer cleaning
- 2. EQUIPMENT Soft hand brush, range of scewdrivers, soft 1" paint brush, suction cleaner with soft brush and nossell fittings, Wet sulction cleaner, Paper towels, Refuse containers, colours coded bucket, Lint free cloths, bottle brushes, safety sign, gloves.

3. METHOD

- a. Display warning sign/ barr- tape
- b.Put on protective gloves (cotton gloves inside rubber gloves)
- c.Switch off appliance to be cleaned
- d.strip down the unit in the manner specified in the Refrigeration cleaning guide supplied.

BY THE MANUFACTURER

- e.clean each part of the unit in the manner specified in the guide.
- f. Replace all parts of the unit in the manner specified in the guide.
- g.pull out the units in order to clean the floor underneath and behind. Replace unit after cleaning the floor.
- h.Switch on appliance and advise customer,s management.
- i.return equipment to allocated storage.
- j.Remove warning sign/ barr-tape
- k.Remove protective gloves