

RISK ASSESSMENT

ULTRA0023

4 Forseeable Hazards

HAZARD	RISK RATING		
	LOW	MEDIUM	HIGH
1 Over filling of batteries		V	
2 Injuries to the public from collision with the buffing machine			V
3 Injuries to the public from contact with buffing machine	√		

5 CONTROLS REQUIRED

Hazard	Essential Controls	Okay with controls
	1 Proper training on safe methods of relevant staff	
	Provision of acid proof gloves for relevant staff	
	2 All relevant staff made aware of pedestrian dangers and	\checkmark
	to be aware at all times of danger	
	Course out alconing of higher density areas outside hyper	
	Carry out cleaning of higher density areas outside busy periods	
	perious	
	Use of warning signs to alert the public	
	coo or mamming origine to allow the parame	
	Use of a flashing amber beacon on the machine to warn	
	the public	
	•	
	Use of public announcements that cleaning is being	
	carried out	
	3 Proper training on safe use techniques of relevant staff	\checkmark